## Fault Abstract for Cycle starting 17 July 2005

Week				Cycle Category
7/17	7/24	7/31	8/7	Total
3.88	0.13	0.61	3.51	8.1 VUV Downtime
0	0	0	0	0.0 VUV Regulation and Compliance Downtime
3.7	2.73	0	0.62	7.1 X-Ray Downtime
0	0	0	0	0.0 X-Ray Regulation and Compliance Downtime
7.83	27.37	0.68	4.2	40.1 Equipment Downtime
X-ray D	owntime .	Areas		Total Type of Problem
0.08				0.08 RF Trips
0.7	0.53		0.62	1.85 Power Dip
2.15	2.2			4.35 Beam Oscillation (Al Dumped on Excursion)
0.02				0.02 Micro/ Network problems
0.75				0.75 Unknown Trip
3.7	2.73	0	0.62	7.05

## 17 July 2005 Cycle Summary

Fill Statistics	X A	U A	X B	U B	X	U	X D	U D	X A	U A
Cycle Starting 17 July 2005	17 .	July	24	July	31 .	July	7 Au	gust	Cycle	Ave
Planned number of User Fills	14	47	11	37	11	47	9	29	11	40
Total Number of User Fills	19	48	18	38	11	47	10	20	15	38
Fills to scheduled completion	9	45	6	36	10	44	7	18	8	36
Dumps during Operations	8	3	10	1	0	3	1	1	4.8	2
Average Time between Faults [hr]	21		18		168		142		88	
Faults Requiring Repairs	1		1		0		1		8.0	
Average Time to Recover [min]	26		18		0		68		28	
Average User Fill Time [min]	35		31		31		30		31	

## Comments on 17 July 2005 Cycle

			ľ
Ring	X	Beam	
Schedule	Α	Avail	
Sunday	0	22.8	
Monday	Ο	22.1	
Tuesday	T/O	18.2	
Wednesday	Ο	22.3	
Thursday	Ο	22.7	
Friday	Ο	22.2	
Saturday	Ο	22.9	
		153.2	•

**Tuesday July 19 very rough on X-ray** 

Beam instabilities causing Active Interlock trips

**Lost Time** 

- > 8 X-ray injection cycles
- Insertion Device Operations Curtailed
- > Feedbacks Disabled

## Several teams launched in parallel to search for cause

July 27 Trim micro became focus of several lines of investigation

CPU Board was replaced July 28, trim glitches ceased

The removed CPU was set up for bench testing

- > Ran for two weeks then failed
- > Probable culprit in series of beam motions

Overall downtime for cycle actually lower than average